

PHENIX Work Permit # DRL-2011-002 Created 1/18/2011: DC FEM Troubleshooting

A handwritten WP Was used to plan the work necessary to allow PHENIX collaborators to work on ladders to affect repairs to DC FEM's during run 11. The work was deemed low ESS&H safety risk, low complexity level and low coordination. Training required was standard PHENIX Awareness and CA Collider user training plus BNL ladder training. No PPE beyond shoes, glasses and gloves where appropriate. There were no radiation concerns, no specific safety and security concerns, no Environmental concerns, no Pollution Prevention Minimization Opportunities, no Facility concerns, no permits and no dosimetry/monitoring required. A back-up watch person was required (as is always the case at PHENIX), and the collaborators were required to be lock out tag out (LOTO) knowledgeable.

The Green WP for this effort was inadvertently misplaced after the work was successfully completed without incident. The work went precisely as planned. Work was completed by 1/31/2011.

This note is placed in the file as a placeholder for the subject WP in the event that the original is located.

Note created by D. Lynch 8/23/2011